Oil Field Environmental Incident Summary

Responsible Party: Continental Resources, Inc.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: LOVDAHL 2-16H

Field Name: SAUK Well File #: 21417

Date Incident:1/16/2014Time Incident:08:57Facility ID Number:County:WILLIAMSTwp:159Rng:95Sec:16Qtr:

Location Description: Lightly misted area to the south-east, approx. 3 acres and across Hwy 50

Submitted By: Stacy Aguirre Received By:

Contact Person: Stacy Aguirre

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	barrels	30	barrels	30	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/14/2016 Clean Up Concluded: 1/17/2014

Risk Evaluation:

none

Areal Extent:

approx. 3 acres to the south-east

Potential Environmental Impacts:

topsoil

Action Taken or Planned:

Contacted NDDOT (Gary Skarpohl, 1/16/14, 8:58), NDIC (John Axtman, 1/16/14, 9:04), and NDDH (Kris Roberts, 1/16/14, 9:11) via telephone to inform agencies of the incident. Misted snow on and around the edge of location and in the Hwy 50 road ditch will be plowed. Landowners were contacted: misted snow east of location will be plowed and melted on location; misted snow south of location, across Hwy 50, received landowner approval for natural attenuation. Kitty litter was applied to the misted road surface.

Wastes Disposal Location:

Agencies Involved: see above under Action Taken

Updates

Date: 1/21/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release sprayed off location, across Hwy 50. Follow-up is necessary. Roberts received call from company contact early in the day to report this due to the location and highway impact. While it was not required that the highway be sanded for traction, Roberts recommended that CRI do it anyway to minimize liability.

Date: 1/23/2014 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/23/2014 at 14:27, on location. Field on east side of wellpad has been scraped up, no noticeable stain on field. No noticeable stain on north side of highway 50 within ditch. Very light stain visible within ditch on south side. Will call report contact to see about plans for this area.

Date: 3/4/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 12:37 3/4/14.

No visible sign of spill.

Confirmation with Russell Martin with NDDoH is necessary to determine whether site is fully remediated.

Date: 6/25/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 6/25/2014.

There is no sign of the spill impacting areas of the well location. The remainder of the stained area is on and near the pumping unit which falls under NDIC jurisdiction.

No followup is necessary.

Date: 3/9/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 9, 2016.